

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission **(Antenna: ANTDP-027A0)**




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

**Radiated Spurious Emission
(Antenna: ANT1267-164C/U-100B)**




Photo 1



Photo 2

**Radiated Spurious Emission
(Antenna: AA222)**




Photo 1






Photo 2

Worst Case Position
(Antenna: ANTDP-027A0)
(Antenna: Horizontal: X0-axis / Vertical: X90-axis)


X0-axis




X90-axis




Y0-axis




Y90-axis



Z0-axis




Z90-axis




Worst Case Position
(Antenna: ANT1267-164C/U-100B)
(Antenna: Horizontal: X-axis / Vertical: Y-axis)


X-axis



Y-axis



Z-axis




Worst Case Position
(Antenna: AA222)
(Antenna: Horizontal: X-axis / Vertical: Y-axis)


X-axis



Y-axis



Z-axis




Worst Case Position

(Module: Horizontal: X-axis / Vertical: X-axis) (Above 1GHz)
(Module: Horizontal: X-axis / Vertical: Z-axis) (Below 1GHz)


X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124