



Color Mode

Tested By: Hong, Report No.: 0001873


Scan Settings (1 Range)

Frequencies			Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten
450k	30M	5k	10k	PK	20ms	AUTO LN OFF 60dB

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Color Mode

Report No.: 0001873

Tested By:Hong, Report No.:0001873

Scan Settings (1 Range)

Frequencies				Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF 60dB

Final Measurement Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV
0.46500	33.2	48.0
0.62500	30.2	48.0
0.77500	27.8	48.0
1.28000	19.7	48.0
1.44000	19.4	48.0
4.63000	26.7	48.0
4.81500	27.2	48.0

* limit exceeded



B/W Mode

Tested By: Hong, Report No.: 0001873


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698





Intertek Testing Services

ETL SEMKO

Color Mode

Report No.: 0001873

Tested By: Hong, Report No.: 0001873

Scan Settings (1 Range)

Frequencies				Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp OpRge
450k	30M	5k	10k	PK	20ms	AUTO LN	OFF 60dB

Final Measurement Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

0.46500	33.2	48.0
0.62500	30.2	48.0
0.77500	27.8	48.0
1.28000	19.7	48.0
1.44000	19.4	48.0
4.68000	26.7	48.0
4.81500	27.2	48.0

* limit exceeded