



Test Setup

FCC ID : NAGSCVX-030821

Internal Photo – 1




Internal Photo - 2




Test Setup

FCC ID : NAGSCVX-030821

Internal Photo – 3




Internal Photo – 4




Test Setup

FCC ID : NAGSCVX-030821

Internal Photo – 5




Internal Photo – 6




Test Setup

FCC ID : NAGSCVX-030821

Internal Photo – 7




Internal Photo – 8




Test Setup

FCC ID : NAGSCVX-030821

Internal Photo – 9



Internal Photo – 10




FCC ID : NAGSCVX-030821


Internal Photo – 13




Internal Photo – 14



Internal Photo – 15




Internal Photo – 16




Test Setup

FCC ID : NAGSCVX-030821

Internal Photo – 17




Internal Photo – 18




Test Setup

FCC ID : NAGSCVX-030821

Internal Photo – 19




Internal Photo – 20



Test Setup

FCC ID : NAGSCVX-030821

Internal Photo – 21



Internal Photo – 22

