

RF EXPOSURE INFORMATION

This receiver is NOT subject to the provisions of 47 CFR 2.1091 for routine environmental evaluation for RF exposure.