



Intertek Testing Services

ETL SEMKO

Report No.: 0301018
Talk Mode

Tested By: Hong, Report No.: 0301018

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement: x QP / + AV


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
----------------	-------	------	------

21	9k	30M	EW0698
----	----	-----	--------



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0301018
Talk Mode

Tested By: Hong, Report No.: 0301018

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement

no Results