



Intertek Testing Services

ETL SEMKO

Report No.: 0206120
Mode: Talk

Tested By: Hong, Report No.: 0206120

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement

no Results