

Dear Dennis :

- (1) Device code corrected . And form 731 resubmitted.
- (2) Corrected label re-submitted.
- (3) Please refer to the test report page 19,20
the first frequency of each table is the power measured by TIA 603 method.
- (4) Page 11 of the test report has a little mistakes about the limit.
Corrected and resubmitted.

TRC

Jacob Lin