

Note that this one system/product has two different labels (one for each line- and phone-module). The difference is only the lack of REN numbers for the phone-module's label since the phone-module does not have a ringer. Please advise whether this is the right approach.

Please find attached two PDF files each of the regulatory labels for phone- and line-modules (18-33-p-rev1.1.pdf & 18-33-l-rev1.1.pdf respectively).

The line-module's label has the REN numbers; the phone-module's label has not. Further, please see the drawing that indicates label placement; each label is placed at the same location of its respective enclosure. Note that the text found on the label in the placement drawing is not current.