1) MBF20 Series Repeater Product labels are generated using the Axell Serial Information System (ASIS) Serial Numbers are assigned according to Part Number and stored in an Electronic database

2) Label templates are designed and attached to each Part Number record in the database. Templates contain Frequency Band Information and FCC Identification. This information is locked to the Part Number by the database.

3) Production Operators have read only access to the database. Part Numbers, Label Templates and their contents are controlled by Axell Engineering and Configuration management.

4) To generate a new serial number login to ASIS (password required) and select Serial Numbers tab. Select the New Button. Enter Operator ID, Part Number and Qty of Labels to generate. Press OK button. Serial Numbers will be generated and added to database.

5) Select Print Button, enter Operator ID, select Serial Number Range and press Next. Labels to be printed will appear on the screen which follows. Confirm the Part Number and Serial range to be printed are correct. Press Print button or Cancel. Printed Labels will be output from the defined Printer for the Label template media.

6) Attach the Product ID Label (yellow) to the right hand side of MBF20. Position label centrally between the M4 CSK screws, 3mm below the casework edge, with text upright as shown.

7) Attach the Standard Serial Number Label (white) immediately to the left of the Product ID Label. Align the bottom edges of both labels leaving a 5mm gap between them.

Date: Wednesday, 12 March 2014	**Product labelling for MBF20 Series**	Not to Scale
© Axell Wireless 2013		Drawn by: JRD
		Issue: 1
Aerial House Asheridge Road Chesham Buckinghamshire HP5 2QD United Kingdom Telephone: +44 (0) 1494 777000 Facsimile: +44 (0) 1494 777002 E-Mail: sales@axellwireless.com www.axellwireless.com		MBF200LB A4

8) Attach the FCC LICENSE WARNING Label to the left hand side of MBF20. Position label centrally between the lid castellations, 3mm below the casework edge, with text upright as shown.
NOTE: This step is only applicable for US Variants currently MBF2000 to MBF2009 only

Date: Wednesday, 12 March 2014

© Axell Wireless 2013

Aerial House
Asheridge Road
Chesham
Buckinghamshire
HP5 2QD United Kingdom

Telephone: +44 (0) 1494 777000
Facsimile: +44 (0) 1494 777002
E-Mail: sales@axellwireless.com
www.axellwireless.com

Product labelling for MBF20 Series

Not to Scale
Drawn by: JRD
Issue: 1

MBF200LB A4


P-touch Editor - [9713000572 rev B Rep Prdct Lbl MBF23072317 FCC+IC.lbl]
File Edit View Insert Format Tools Layout Window Help
Brother PT-9700PC
Standard
Print
Normal Format
104 mm
24 mm
2 mm
Arial
16
Professional
axell WIRELESS
Model: Description
OPERATING FREQUENCIES AND VOLTAGES
FreqRange
PowerInfo
BARCODE
FCC ID: NEOMBF23072317
IC: 8749A-MBF23072317
Origin
RegDate
24 mm
Ark 1
Snap
Express
Professional
Brother PT-9700PC
300 %

axell WIRELESS

Model: MBF-2307-2317-M-1510

OPERATING FREQUENCIES AND VOLTAGES

698-787, 728-756,1710-1755, 2110-2155 MHz
15V 3A DC

FCC ID: NEOMBF23072317
IC: 8749A-MBF23072317

MBF2006A/DPFB

Made in uk 2014-03-21

axell WIRELESS

Model: MBF-2307-2317-M-1530

OPERATING FREQUENCIES AND VOLTAGES

698-787, 728-756,1710-1755, 2110-2155 MHz
15V 3A DC

FCC ID: NEOMBF23072317
IC: 8749A-MBF23072317

MBF2007A/DPFC

Made in uk 2014-03-21

axell WIRELESS

Model: MBF-2307-2317-M-1550

OPERATING FREQUENCIES AND VOLTAGES

698-787, 728-756,1710-1755, 2110-2155 MHz
15V 3A DC

FCC ID: NEOMBF23072317
IC: 8749A-MBF23072317

MBF2008A/DL1G

Made in uk 2014-03-12

axell WIRELESS

Model: MBF-2307-2317-M-1570

OPERATING FREQUENCIES AND VOLTAGES

698-787, 728-756,1710-1755, 2110-2155 MHz
15V 3A DC

FCC ID: NEOMBF23072317
IC: 8749A-MBF23072317

MBF2009A/DPFD

Made in uk 2014-03-21

WARNING. This is NOT a CONSUMER device.
It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC LICENSEE to operate this device. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of $100,000 for each continuing violation.