

11/23/2001

A-Pex International

In reference to FCC ID: NHVB1U523

Mr. Kosaka

Upon completion of review of the FCC ID NHVB1U523 is in process and the following is needed before the review can begin.

Please address each issue below.

- 1.) A new copy of the test report, several pages did not convert properly and the data is unreadable. Please resubmit new report as soon as possible to continue this review.

David A. Case NCE
Examining Engineer
<mailto:dcase@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination.

Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.