

To: "Timothy R. Johnson" <TRJ@adelphia.net>
Subject: Re: Review of FCC ID: NHVWBJ443

Tim,

Could you confirm the following answer?

>The automatic deactivation in the report shows about 300 ms. Is this for
>manual mode?

---->> Yes, this is manual mode.

>If so, please provide a plot that shows deactivation in < 50 msec as
>specified below for transmissions in response to the 125 kHz signal.

---->> Please find attached file. This is data for transmissions in
response to the 125 kHz signal.

RFEN is a output carrier, and the data is modulated with "FSK". In front of
this data, there is about 2mS's signal. This signal is called
"anti-collision" and is used for the confirmation which Hand Unit answered.
<Since one control unit can register 4 hand unit max, data causes
interference if they answer at the same time.>

The above answer is acceptable? I hope the grant is issued with this.

Thank you very much.

Best regards,

Yukie Koyama

.....

EMC Head Office Division
A-Pex International Co.,Ltd.
4383-326 Asama-cho Ise-shi
Mie-ken 516-0021 JAPAN
TEL +81-596-24-8116
FAX +81-596-24-8124
E-mail:ykoyama@a-pex.co.jp

.....

--Original Message 2003/02/06 7:20:50--

Yukie,

The automatic deactivation in the report shows about 300 ms. Is this for
manual mode?

If so, please provide a plot that shows deactivation in < 50 msec as
specified below for transmissions in response to the 125 kHz signal.

Thank You,