



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

November 10, 2004

RE: Senao International Co., Ltd..

FCC ID: NI3-AT30V514

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Please carefully review page 15 and 26 of the users manual. These pages show the device is capable of 802.11a TX (5 GHz Wireless Mode and TX power). This application does not include 5 GHz TX information. If this device includes this, additional testing will be necessary to include this. Please correct as necessary.
- 2) Please carefully review page 26 of the users manual. These pages show the device is capable of Turbo Mode (Super G). This application does not include this. If this device includes this, additional testing will be necessary to include this. Please correct as necessary
- 3) The measurement reported on page 20 for Position 5, Middle channel does not match the plot (data shows 0.768, plot shows 0.786). Please review.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.