

TOYOTA

TOYOTA MOTOR CORPORATION

1, TOYOTA-CHO, TOYOTA, AICHI, 471-8571(Head Office)
or 471-8572(Research & Development Group) JAPAN
TEL : (0565)28-2121

Toyota Motor Corporation
1, Toyota-cho, Toyota, Aichi, 471-8572 Japan

Date: July 27, 2004

Subject: Compliance Statement in Car manual

FCC ID:NI4TMLF-1
FCC ID:NI4TMLF-2

IC:2842-TMLF1
IC:2842-TMLF2

Dear Sirs,

Our products with the above FCC ID codes are low-frequency transmitters. The products will have been installed in cars before they are placed into the market.

We hereby assure that the following caution statement as per CFR47, Part 15, Paragraph 15.21 is included in the owner's manuals of the cars:

The title "CAUTION TO USER" or "FCC WARNING:" "NOTE:" or relevant title and "Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment."

In addition, we also assure that the following statement is also included in the manuals as per CFR 47, Part 15, Paragraph 15.19(a)(3):

This device complies with Part 15 of the FCC Rules and with RSS-210 of Industry Canada. Operation is subject to the following two conditions:

- 1) This device may not cause harmful interference
- 2) This device must accept any interference received including interference that may cause undesired operation.

Yours sincerely,



Tomoaki Katayama, Toyota Motor Corporation
Telephone Number: +81-565-23-9304
Fax Number: +81-565-23-7505