


### **APPENDIX 3: Photographs of test setup**

#### **Radiated Spurious Emission**



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

### Worst Case Position

#### ECU

Below 30 MHz:

X-axis

Above 30 MHz:

Horizontal: X-axis / Vertical: X-axis

**X-axis**



**Y-axis**



**Z-axis**



#### Door Antenna

Below 30 MHz:

X-axis


Above 30 MHz:

Horizontal: X-axis / Vertical: X-axis


**X-axis**



**Y-axis**



**Z-axis**



### Worst Case Position

#### Trunk Antenna

Below 30 MHz:

X-axis

Above 30 MHz:

Horizontal: X-axis / Vertical: X-axis

**X-axis**



**Y-axis**



**Z-axis**



#### Room Antenna / Luggage Antenna


Below 30 MHz:

X-axis

Above 30 MHz:

Horizontal: X-axis / Vertical: X-axis


**X-axis**



**Y-axis**



**Z-axis**



**End of Report**

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124