

APPENDIX 3: Photographs of test setup

Radiated Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position (Axes)

ECU
Below 30 MHz:
X-axis
Above 30 MHz:
Horizontal: X / Vertical: X


X-axis



Y-axis



Z-axis



Outside Antenna

Below 30 MHz:
X-axis
Above 30 MHz:
Horizontal: X / Vertical: X

X-axis



Y-axis



Z-axis



UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position (Axes)

Inside Antenna

Below 30 MHz:

X-axis

Above 30 MHz:

Horizontal: X / Vertical: X

X-axis



Y-axis



Z-axis



Rear Antenna

Below 30 MHz:

X-axis

Above 30 MHz:

Horizontal: X / Vertical: X

X-axis



Y-axis



Z-axis



Worst Case Position (Axes)

Immobilizer Antenna

Below 30 MHz:

X-axis

Above 30 MHz:

Horizontal: X / Vertical: X

X-axis



Y-axis



Z-axis



Worst Case position (Immobilizer)



Without Key (Worst)



With Key

End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124