





2.7 PHOTOS OF CONDUCTION TEST

(1) For Printer port





Industrial Technology Research Institute
Electronics Research & Service Organization
Bldg. 17, 195-4 Sec. 4, Chung Hsing Rd., Chutung, Hsinchu, 310
Taiwan, Republic Of China
TEL : 886-3-5917069 FAX : 886-3-5825720



FCC ID : NJCDP36VC

Report No. : ESM-8806-002F

Page 12 of 20

2.7 PHOTOS OF CONDUCTION TEST

(2) For USB port





3.7 PHOTOS OF OPEN SITE

(1) For Printer port





Industrial Technology Research Institute

Electronics Research & Service Organization

Bldg. 17, 195-4 Sec. 4, Chung Hsing Rd., Chutung, Hsinchu, 310

Taiwan, Republic Of China

TEL : 886-3-5917069 FAX : 886-3-5825720

FCC ID : NJCDP36VC

Report No. : ESM-8806-002F

Page 18 of 20

3.7 PHOTOS OF OPEN SITE


(1) For Printer port





3.7 PHOTOS OF OPEN SITE

(2) For USB port





Industrial Technology Research Institute
Electronics Research & Service Organization
Bldg. 17, 195-4 Sec. 4, Chung Hsing Rd., Chutung, Hsinchu, 310
Taiwan, Republic Of China
TEL : 886-3-5917069 FAX : 886-3-5825720

FCC ID : NJCDP36VC

Report No. : ESM-8806-002F

Page 20 of 20

3.7 PHOTOS OF OPEN SITE

(2) For USB port

