



Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch
香港商立德國際商品試驗有限公司 桃園分公司

No. 19, Hwa Ya 2nd Rd., Wen Hwa Tsuen, Kwei Shan Hsiang, Taoyuan Hsien 33383, Taiwan

TEL: 886-3-3183232 FAX: 886-3-3270892

www.bureauveritas-adt.com / E-mail: service.adt@tw.bureauveritas.com

Date: November 30, 2020

SUBJECT: Supersede for FCC ID: NKS-MA1BA1TE1, Granted: 11/26/2020

To Whom It May Concern:

We regret to inform you that due to a typo in the model names within the test reports, we would like to supersede the following documents listed below to prevent a misunderstanding to the public:

Original Exhibit Name	Revised Exhibit Name	Correction
RF Exposure Info (MPE) rev.pdf	RF Exposure Info (MPE) rev2.pdf	Section 2
Test Report (DFS-Client-Spot Check).pdf	Test Report (DFS-Client-Spot Check) rev.pdf	Section 2
Test Report (DSS-BT EDR-Spot Check).pdf	Test Report (DSS-BT EDR-Spot Check) rev.pdf	Section 3.1
Test Report (DTS-BT LE-Spot Check).pdf	Test Report (DTS-BT LE-Spot Check) rev.pdf	Section 3.1
Test Report (DTS-WLAN-Spot Check).pdf	Test Report (DTS-WLAN-Spot Check) rev.pdf	Section 3.1
Test Report (NII-Spot Check).pdf	Test Report (NII-Spot Check) rev.pdf	Section 3.1
Test Report (Part 22_WCDMA 5-Spot Check).pdf	Test Report (Part 22_WCDMA 5-Spot Check) rev.pdf	Section 3.1
Test Report (Part 24_WCDMA & LTE 2-Spot Check).pdf	Test Report (Part 24_WCDMA & LTE 2-Spot Check) rev.pdf	Section 3.1
Test Report (Part 27_WCDMA & LTE B4.12-Spot Check) rev.pdf	Test Report (Part 27_WCDMA & LTE B4.12-Spot Check) rev2.pdf	Section 3.1

Erroneous mentions of Trimble Gateway-MA2 / Trimble Gateway-BA2 / Trimble Gateway-TE2 have been corrected to Trimble Gateway-MA1 / Trimble Gateway-BA1 / Trimble Gateway-TE1.

If you have any questions, feel free to contact us. Thank you.

Best Regards,

Anson Lin

Anson Lin / Project Engineer

Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch

Tel: 886-3-318 3232

Fax: 886-3-327 0892

Email: anson.lin@bureauveritas.com