

Mike Kuo

From: daphne.liang [daphne.liang@tw.ccsemc.com]
Sent: Monday, January 02, 2006 9:39 PM
To: application@tw.ccsemc.com; Mike Kuo
Cc: lucy.tsai
Subject: Re : Re : FW: Billionton Systems Inc., FCC ID: NLF-GCBBTCR41X, Assessment NO.: AN05T5386, Notice-Updated(0103)final
Importance: High
Attachments: GCBBTCR41X-YY-ZZZ_SCH(0103).pdf; GCBBTCR41X-YY-ZZZ_User manual(0103).pdf; GCBBTCR41X-YY-ZZZ_Antenna Spec(0103).pdf; GCBBTCR41X-YY-ZZZ_Setup Photo(0103).pdf; GCBBTCR41X-YY-ZZZ_Report(RP1-1)final 0103.pdf

Dear Mike:

Sorry for my mistake,I forgot to update the antenna gain as -0.13dBi.
Please find the final version of test report.

BEST REGARDS

Daphne Liang / 梁鈺如 01/03/2006
Certification Team Leader / R&D and Certification Dept.

Compliance Certification Services Inc.
Rm.258, Bldg.17, No.195, Sec.4, Chung
Hsing Rd.,Chutung,Hsinchu,Taiwan,R.O.C.
Tel: 886-3-5910068 EXT: 502
Fax: 886-3-5825720
E-mail: daphne.liang@tw.ccsemc.com
URL: <http://www.ccsemc.com.tw>

daphne.liang

梁玉如	收件人 :	mkuo@ccsemc.com, application@tw.ccsemc.com
	副本抄送 :	lucy.tsai/ccsemc@ccsemc
2006/01/03 01:30 PM	主旨 :	Re : FW: Billionton Systems Inc., FCC ID: NLF-GCBBTCR41X, Assessment NO.: AN05T5386, Notice--Updated(0103) 連結

Dear Mike:

Thank you for your e-mail.Please see the belowing reply and find the updated files(0103) as attached.

If still have any problems,please let me know,thank you for your support~

1/3/2006

BEST REGARDS

Daphne Liang / 梁鈺如 01/03/2006
Certification Team Leader / R&D and Certification Dept.

Compliance Certification Services Inc.
Rm.258, Bldg.17, No.195, Sec.4, Chung
Hsing Rd., Chutung, Hsinchu, Taiwan, R.O.C.
Tel: 886-3-5910068 EXT: 502
Fax: 886-3-5825720
E-mail: daphne.liang@tw.ccsemc.com
URL: http://www.ccsemc.com.tw

lucy.tsai

蔡文君

收件人: daphne_liang/ccsemc

副本抄送:

主旨: FW: Billinton Systems Inc., FCC ID: NLF-GCBBTCR41X, Assessment NO.: AN05T5386, Notice

2006/01/02 05:27 PM

----- 轉呈者 lucy.tsai/ccsemc 於 2006/01/02 05:20 PM -----

"Mike Kuo" <mike.kuo@ccsemc.com>

2005/12/28 04:19 AM

收件人: "daphne.liang" <daphne.liang@tw.ccsemc.com>, "application" <application@tw.ccsemc.com>

副本抄送: "lucy.tsai" <lucy.tsai@tw.ccsemc.com>

主旨: FW: Billinton Systems Inc., FCC ID: NLF-GCBBTCR41X, Assessment NO.: AN05T5386, Notice

Question #1: Schematic diagram is not complete. Please submit complete schematic diagram.

Ans: Please find the attached for updated SCH(0103).

Question #2: Based upon the screen shots contain in the user manual, submitted user manual is written for Toshiba but Toshiba is not one of manufacturer listed in the multiple listing section. In addition, most of screen shots are not clear, please make sure to submit a clear version of user manual.

Ans: Please find the attached for updated User manual(0103).

Question #3: User manual does not contains information required per section 15.21 of FCC rules. In addition, since this device is also classified as digital device, statement listed in section 15.105(b) is also required.

Ans: Please find the attached for updated User manual(0103) of page 160.

Question #4: All the values listed in the antenna specification can not be read. Please submit a clear version of antenna specification.

Ans: Please find the attached for updated Antenna Spec.(0103).

Question #5: Section 2.1 of test report, the output power listed in the RF exposure section does not agree with measured output power. Please explain.

Ans: Please find the attached for updated test report(0103)final of page 4.

And setup photo(0103)

Question #6: Device is capable of various data rate, which data rate was selected for the final tests and justification of the worst case.

Ans: Please find the attached for updated test report(0103)final.

Since our client's software can not support any more even the Air Data Rate in specification is up to 8-DPSK (3Mbps)!!

So we measurement the Air Data Rate is GFSK (1Mbps) and selected for the final tests.

Best Regards

Mike Kuo

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission, Thank you for your attention.