



daphne.liang

梁玉如

2005/08/29 03:24 PM

收件人: Mike Kuo <mike.kuo@ccsemc.com>
副本抄送: application/ccsemc@ccsemc,
主旨: Re: Billinton Systems Inc., FCC ID: NLF-GUBTCR41E ,
Assessment NO.: AN05T5096, Notice#1--Updated(0829) 

Dear Mike:

Thank you for your e-mail. Please find the attached for updated(0829).
And if still have any problems, please connect with me.

BEST REGARDS

Daphne Liang / 梁鈺如 8/29/2005
Certification Team Leader / R&D and Certification Dept.

Compliance Certification Services Inc.
Rm.258, Bldg.17, No.195, Sec.4, Chung
Hsing Rd., Chutung, Hsinchu, Taiwan, R.O.C.
Tel: 886-3-5910068 EXT: 502
Fax: 886-3-5825720
E-mail: daphne.liang@tw.ccsemc.com
URL: <http://www.ccsemc.com.tw>



**"Compliance
Certification Services"**
<mike.kuo@ccsemc.com>

2005/08/26 01:33 PM

收件人: daphne.liang@tw.ccsemc.com
副本抄送:
主旨: Billinton Systems Inc., FCC ID: NLF-GUBTCR41E , Assessment
NO.: AN05T5096, Notice#1

Hi Daphne,

Please address the following issues.

Question#1: Please go over all test dates indicated in test report, several items can't match the test period indicated in page 3.

Ans: Please find the attached for updated: GUBTCR41E_Report(FCC Part15C)0829.

Question#2: Please demonstrate this product conforms to RF exposure requirement.

Ans: Please find the attached for updated: GUBTCR41E_Report(FCC Part15C)0829.

(Remarked the RF Exposure Evaluation on page 4)

Best Regards,
Mike Kuo

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission, Thank you for your attention.

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission, Thank you for your attention.

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission, Thank you for your attention.