



1204, Changwon-daero, Seongsan-gu Changwon-si Gyeongsangnam-do, South Korea  
T. 82-70-7147-8361 F. 82-31-8108-3717


Date: February 11, 2016

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia MD 21046

Subject: Class II Permissive change

This is to request a Class II permissive change as following FCC ID. The product is no hardware modifications. Added to the product is AC adapter

| Applicant Name           | Model name | FCC ID       | Date of Grant |
|--------------------------|------------|--------------|---------------|
| Hanwha Techwin Co., Ltd. | SEW-3040W  | NLMSEW3040W  | 2014.06.13    |
|                          | SEB-101ARW | NLMSEB1019RW | 2015.04.27    |
|                          | SEW-3041W  | NLMSEW3041W  | 2014.06.13    |
|                          | SEP-1002RW | NLMSEP1001RW | 2015.04.28    |



As the change does not effect the rf characteristics, the original RF exposure report remains valid.

If you have any questions regarding this application, please feel free to contact me

Sincerely Yours,

Jeisoon Kang / Principal Research Engineer  
Hanwha Techwin Co., Ltd.