



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

February 20, 2003

RE: Allstar Corporation

FCC ID: NM483AQCT04

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) The test report provides information regarding modifications that were made, but the cover letters provided. Please confirm whether modifications were or were not required and correct the affected exhibits.
- 2) The device appears to contain 10 pulses instead of 12 as given in section 6.1. Note that the calculation actually appears correct for 10 pulses although the sample calculation states 12. Please correct.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.