

RE: Allstar Corporation
FCC ID: NM483AQCT04

Response to comments on the above referenced Application.

1) The test report provides information regarding modifications that were made, but the cover letters provided. Please confirm whether modifications were or were not required and correct the affected exhibits.

A corrected Attestations exhibit has been uploaded.

2) The device appears to contain 10 pulses instead of 12 as given in section 6.1. Note that the calculation actually appears correct for 10 pulses although the sample calculation states 12. Please correct.

A corrected Test Report has been uploaded.