



Intertek Testing Services

ETL SEMKO

Report No.: 9903702

Made: Charging

Tested By: Hong, Report No.: 9903702

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: X QP

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

dBuV

80

70

60

50


40

30

20

10

0



FCC15B

0.45

1

10

20

MHz

PAGE 1

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9903702

Mode: Charging

Tested By: Hong, Report No.: 9903702

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9903702

Mode: Standby

Tested By: Hong, Report No.: 9903702


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRgs
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: X QP

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB



PAGE 1

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9903702

Made: Standby

Tested By: Hong, Report No.: 9903702

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9903702
Mode: Transmission

Tested By: Hong, Report No.: 9903702

Scan Settings (1 Range)

----- Frequencies ----- Receiver Settings -----

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: X QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



PAGE 1

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9903702

Mode: Transmission

Tested By: Hong, Report No.: 9903702

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
28.64000	29.6	48.0

* limit exceeded

Ctrl. No.: N/A