

Report No.: 99009971

Mode: Charging

Tested by: Hong, Report No.: 99009971

Scan Settings (1 Range)

----- Frequencies ----- Resolution ----- Resolution Settings -----

Start	Stop	Step	IF BW	Detector	RefTime	atten	Presamp	Gate
450k	30M	5k	100	PK	0.000	ADPTD	LB OFF	60dB


Final Measurement: Noise

Transducer	Ref	Start	Stop	Name
2	OK	30M		E1078

Meas Time: 1.5

Subrange: 16

Acc. Margin: 20dB



Report No.: 99009971

Mode: Charging

Tested By: Hong, Report No.: 99009971

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:


Frequency	QP Level	QP Limit
MHz	dBuV	dBuV
29.48500	33.9	48.0

* limit exceeded

Ctrl. No.: N/A

Mode! Standby

Final Measurements: 1.0M	Time (min): 10.00	Temp: 30.4	Name: E1078
Meas Time: 1.0			
Sample Weight: 1.0			
Acc. Balance: 10.0g			



Report No.: 99009971
Mode: Standby

Tested By: Hong, Report No.: 99009971

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
29.48500	34.3	48.0

* limit exceeded

Ctrl. No.: N/A

Mode: Transmissions

Age Group: 20-30





Intertek Testing Services

ETL Testing Laboratories

Report No.: 99009971

Mode: Transmission

Tested By: Hong, Report No.: 99009971

Scan Settings (1 Range)

|----- Frequencies -----|----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
29.48500	35.6	48.0

* limit exceeded

Ctrl. No.: N/A