





880405

FCC ID:NRPPK351AN

Mechanical Construction


Reference modification letter No.2





880405

FCC ID:NRPPK351AN


Mechanical Construction



880405



880405



880405

FCC ID:NRPPK351AN

Rear side of main Board