

Mode = TX

Report No.: 9808543

Tested By: Hong, Report No.: 9808543


Scan Settings (1 Range)

Frequencies				Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge	
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB	

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



PAGE 1

Ctrl. No.: N/A

FCC ID: NS2MH9006

ITS Intertek Testing Services

ETL Testing Laboratories

Mode = TX

Report No.: 9808543

Tested By: Hong, Report No.: 9808543

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
25.80500	31.2	48.0

* limit exceeded

Ctrl. No.: N/A

Mode: Stand-by

Report No.: 9808543

Tested By: Hong, Report No.: 9808543

Scan Settings (1 Range)

Frequencies				Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge	
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB	


Final Measurement: X QP

Transducer No.	Start	Stop	Name
3	9k	30M	E1078

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB



Ctrl. No.: N/A

ITS Intertek Testing Services

ETL Testing Laboratories

Mode: Stand-by

Report No.: 9808543

Tested By: Hong, Report No.: 9808543

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
25.80500	30.6	48.0

* limit exceeded

Ctrl. No.: N/A

FCC ID: NS2MH9006

Mode: Charging

Report No.: 9808543

Tested By: Hong, Report No.: 9808543

Scan Settings (1 Range)

Frequencies			Receiver Settings				
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF -60dB


Final Measurement: X QP

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB



PAGE 1

Ctrl. No.: N/A

FCC ID: NS2MH9006

Mode: Charging

Report No.: 9808543

Tested By: Hong, Report No.: 9808543

Scan Settings (1 Range)

----- Frequencies -----			----- Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV
15.48500	27.1	48.0

* limit exceeded

Ctrl. No.: N/A