



Intertek Testing Services

ETL SEMKO

Report No.: 0004237 *Transmit Mode*

Tested By: Hong, Report No.: 0004237

Scan Settings (1 Range)

----- Frequencies ----- Receiver Settings -----

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: xQP


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

21 9k 30M EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0004237 *Transmit Mode*

Tested By: Hong, Report No.: 0004237

Scan Settings (1 Range)

|----- Frequencies -----| |----- Receiver Settings -----|

Start Stop Step IF BW Detector M-Time Atten Preamp OpRge

450k 30M 5k 10k PK 20ms AUTO LN OFF 60dB

Final Measurement Results:

Frequency QP Level QP Limit

MHz dBuV dBuV

0.54000 33.8 48.0

0.59000 32.2 48.0

0.75500 21.9 48.0

* limit exceeded

Ctrl No.: N/A