

ITS Intertek Testing Services

ETL Testing Laboratories

Mode: TX
Model: MH9006

Report No.: 9810976

Tested By: Hong, Report No.: 9810-547


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	100k	AUTO	LN OFF	60dB

Final Measurement: X OF

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Wave Time: 1 s
Subslices: 16
Ave Height: 20dB



PAGE 1

Ctrl. No.: N/A

FCC ID: NS2MH9006N

ITS Intertek Testing Services

ETL Testing Laboratories

Mode = TX
Model = MH9006

Report No.: 9810976

Tested By: Hong, Report No.: 9810547

Scan Settings (1 Range)

----- Frequencies -----			----- Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	10ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A

FCC ID: NS2MH9006N

ITS Intertek Testing Services

ETL Testing Laboratories

Mode = Stand by
Model = MH9006

Report No.: 9810976

Tested By: Hong, Report No.: 9810547

Scan Settings (I Range)

Frequencies			Receiver Settings						
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge	
450k	30M	5k	10k	PK	10ms	AUTO	LN OFF	60dB	


Final Measurement: X QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	E1078



PAGE 1

Ctrl. No.: N/A

FCC ID: NS2MH9006N

ITS Intertek Testing Services

ETL Testing Laboratories

Mode = Stand by
Model = MH9006

Report No.: 9810976

Tested By: Hong, Report No.: 9810547

Scan Settings (1 Range)

----- Frequencies -----			----- Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	10ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A

FCC ID: NS2MH9006N

ITS Intertek Testing Services

ETL Testing Laboratories

Mode: Charging
Model: MH9006

Report No.: 9810976

Tested By: Hong, Report No.: 9810547

Scan Settings (1 Range)

Frequencies			Receiver Settings						
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge	
450k	30M	5k	10K	PK	10ms	AUTO	LN	OFF 60dB	

Final Measurement: N-QP

Meas Time: 1 s


Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

3 9k 30M

EI078



PAGE 1

Ctrl. No.: N/A

FCCID: NS2MH9006N

ITS Intertek Testing Services

ETL Testing Laboratories

Mode = Charging
Model = MH9006

Report No.: 9810976

Tested By: Hong, Report No.: 9810547

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	10ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A

FCC ID: NS2MH9006N