



Intertek Testing Services

ETL SEMKO

Report No.: 9904160


Mode: Charging

Tested By: Hong, Report No.: 9904160
Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRqd
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF

Final Measurement:	x	QP	Transducer No.	Start	Stop	Name
			3	9k	30M	EI078

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB





Intertek Testing Services

ETL SEMKO

Report No.: 9904160

Mode: Charging

Tested By: Hong, Report No.: 9904160

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9904160


Mode: Standby

Tested By: Hong, Report No.: 9904160

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: X QP		Transducer No.	Start	Stop	Name
Meas Time:	1 s	3	9k	30M	EI078
Subranges:	16				
Acc Margin:	20dB				



Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9904160

Mode: Standby

Tested By: Hong, Report No.: 9904160

Scan Settings (1 Range)

----- Frequencies -----			----- Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9904160

Mode: Transmission

Tested By: Hong, Report No.: 9904160

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: * QP


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

dBuV



PAGE 1

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9904160

Mode: Transmission

Tested By: Hong, Report No.: 9904160

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
21.49500	27.2	48.0

* limit exceeded

Ctrl. No.: N/A