



Intertek Testing Services -Menlo Park

Casil Technology Taiwan Ltd., 900 MHz Cordless Telephone
FCC ID: NSJCTT-900AB

Date of Test: May 5 & 15, 1998

3.2 Radiated Emission Configuration Photograph

Worst Case Radiated Emission
at 916.275 MHz





Intertek Testing Services -Menlo Park

Casil Technology Taiwan Ltd., 900 MHz Cordless Telephone
FCC ID: NSJCTT-900AB

Date of Test: May 5 & 15, 1998

3.2 Radiated Emission Configuration Photograph - (Continued)

Worst Case Radiated Emission
at 916.275 MHz




Intertek Testing Services -Menlo Park

Casil Technology Taiwan Ltd., 900 MHz Cordless Telephone
FCC ID: NSJCTT-900AB

Date of Test: May 5 & 15, 1998

3.2 Radiated Emission Configuration Photograph - (Continued)

Worst Case Radiated Emission
at 916.275 MHz



Intertek Testing Services -Menlo Park

Casil Technology Taiwan Ltd., 900 MHz Cordless Telephone
FCC ID: NSJCTT-900AB

Date of Test: May 5 & 15, 1998

3.4 AC conducted Emission Configuration Photograph

Worst Case Conducted Emission
at 1.221 MHz

