



RSC-900 Sch

Tadiran Telematics Proprietary

Tadiran Telematics Proprietary - Commercial Confidential

RSC-900

Road Side Communicator Photographs

Proposed for
FCC Type Approval

Page 1 of 16


Tadiran Telematics Ltd., 26 Hamelacha St., P.O.B. 1911, Holon 58117, Israel

Tel.: (972-3) 557-5722 Fax.: (972-3) 557-5753

E-Mail: hanan@tadiran-telematics.com

1. CPU

1.1 Component Side



Tadiran Telematics Ltd., 26 Hamelacha St., P.O.B. 1911, Holon 58117, Israel

Tel.: (972-3) 557-5722 Fax.: (972-3) 557-5753

E-Mail: hanan@tadiran-telematics.com

t

RSC-900 Sch

Tadiran Telematics Proprietary



Page 3 of 16

Tadiran Telematics Ltd., 26 Hamelacha St., P.O.B. 1911, Holon 58117, Israel


Tel.: (972-3) 557-5722 Fax.: (972-3) 557-5753

E-Mail: hanan@tadiran-telematics.com

t

RSC-900 Sch

Tadiran Telematics Proprietary



Tadiran Telematics Ltd., 26 Hamelacha St., P.O.B. 1911, Holon 58117, Israel

Tel.: (972-3) 557-5722 Fax.: (972-3) 557-5753

E-Mail: hanan@tadiran-telematics.com

t

RSC-900 Sch

Tadiran Telematics Proprietary




Page 5 of 16

Tadiran Telematics Ltd., 26 Hamelacha St., P.O.B. 1911, Holon 58117, Israel


Tel.: (972-3) 557-5722 Fax.: (972-3) 557-5753

E-Mail: hanan@tadiran-telematics.com

1.2 Print Side



Tadiran Telematics Proprietary




Tel.: (972-3) 557-5722 Fax.: (972-3) 557-5753

R:\Tadiran Telematics\14963\FCC application\RSCW900 Photos new.doc

t

RSC-900 Sch

Tadiran Telematics Proprietary



Page 8 of 16

Tadiran Telematics Ltd., 26 Hamelacha St., P.O.B. 1911, Holon 58117, Israel


Tel.: (972-3) 557-5722 Fax.: (972-3) 557-5753

E-Mail: hanan@tadiran-telematics.com

t

RSC-900 Sch

Tadiran Telematics Proprietary



Page 9 of 16

Tadiran Telematics Ltd., 26 Hamelacha St., P.O.B. 1911, Holon 58117, Israel

Tel.: (972-3) 557-5722 Fax.: (972-3) 557-5753

E-Mail: hanan@tadiran-telematics.com

2. DMU

2.1 Component Side



Ta


8117, Israel

Tel.: (972-3) 557-5722 Fax.: (972-3) 557-5753
E-Mail: hanan@tadiran-telematics.com

t

RSC-900 Sch

Tadiran Telematics Proprietary




of 16

St., P.O.B. 1911, Holon 58117, Israel

Fax.: (972-3) 557-5753

an-telematics.com

2.2 Print Side



3. RFU

2.1 Component Side (with and without RF shield)




7, Israel

E-Mail: hanan@tadiran-telematics.com

t

RSC-900 Sch

Tadiran Telematics Proprietary



Page 14 of 16

Tadiran Telematics Ltd., 26 Hamelacha St., P.O.B. 1911, Holon 58117, Israel


Tel.: (972-3) 557-5722 Fax.: (972-3) 557-5753

E-Mail: hanan@tadiran-telematics.com

t

RSC-900 Sch

Tadiran Telematics Proprietary



Page 15 of 16

Tadiran Telematics Ltd., 26 Hamelacha St., P.O.B. 1911, Holon 58117, Israel

Tel.: (972-3) 557-5722 Fax.: (972-3) 557-5753

E-Mail: hanan@tadiran-telematics.com

2.3 Print Side

