

Mike Kuo

From: Claire Hoque
Sent: May 18 2004 1:40 PM
To: Mike Kuo
Cc: Helen Zhao; Mika Kaneko
Subject: RE: TOKO, Inc., FCC ID:NUSTMW1059, AN04T3903



Antenna location
photos.pdf

Hi Mike,

Here are the answers.

Question #1: The antenna position can not be located in the internal photos.
Please identify antenna location in the internal photos or provide
additional photo to show antenna location.
<answer>pls see the antenna location photos.

Question #2: How is the antenna connected to the cardbus ? Is it via antenna
connector ? If yes, please provide antenna connector specification.
<answer>The antenna is integrated in a card.

Thanks,

Claire

-----Original Message-----

From: CERTADM
Sent: Monday, May 17, 2004 11:40 PM
To: Mike Kuo
Subject: TOKO, Inc., FCC ID:NUSTMW1059, AN04T3903

Notice_content

Question #1: The antenna position can not be located in the internal photos.
Please identify antenna location in the internal photos or provide
additional photo to show antenna location.

Question #2: How is the antenna connected to the cardbus ? Is it via antenna
connector ? If yes, please provide antenna connector specification.

Best Regards

Mike Kuo

The items indicated above must be submitted before processing can continue
on the above referenced application. Failure to provide the requested
information within 30 days of the original e-mail date may result in
application dismissal and forfeiture of the filing fee. Also, please note
that partial responses increase processing time and should not be submitted.
Any questions about the content of this correspondence should be directed to
the e-mail address listed below the name of the sender.