

September 2, 1999

FCC
Equipment Authorization Division
Applications Processing Branch
7435 Oakland Mills Road
Columbia, MD 21046

Ref: FCC ID Correction Request
Confirmation #EA95313

Attn: Betty Taube

Dear Betty,

When electronically filing for Certification of the Cellular Specialties Mini Bidirectional Amplifier the final digits of the equipment product code were inadvertently left off. We listed the product code as "CSI110" when it should have been "CSI110-01". Please add the "-01" to end of the product code to make the complete FCC ID read: NVRCSI110-01.

Thank you for your attention to this matter. If you should have any questions please contact me at 603-497-4600 or by e-mail at retlif-nh@empire.net.

Sincerely,

RETLIF TESTING LABORATORIES

Scott Wentworth
NH Branch Manager

INTERMODULATION