



TIMCO Engineering Inc
849 NW State Road 45
Newberry FL 32669
USA

Date: August 13, 2019

Subject: Change in FCC ID per 47 CFR Section 2.933
FCC ID: NVRPSA91080-S8X

Warning Label Attestation

Warning label messages and Class A/B disclosure will be also shown in online and point-of-sale marketing materials and on outside packaging of device.

Part 90 Signal Boosters	THIS IS A 90.219 CLASS A DEVICE
WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.	

Regards

Joe Gage
Compliance Engineer