




Note: RF receiver has no internal/external crystal frequencies

## 8040 Radio Transceiver

April, 98

L.R. Nelson Confidential