

Jack Tsai

寄件者: Tim Tai <tim_tai@solomon.com.tw>
收件者: Jack Tsai <jack@trclab.com.tw>
傳送日期: 2002年2月4日 PM 06:25
附加檔案: P1-10.pdf; p11-23.pdf; p24-34.pdf; p35-36.pdf; p37-39.pdf; p40-45.pdf
主旨: Re: SAR problem

Jack,

Please help me to check the statement as following item 2 if it is correct.

Thanks and regards,
Tim

----- Original Message -----

From: Jack Tsai <jack@trclab.com.tw>
To: Tim Tai <Tim_Tai@solomon.com.tw>
Sent: Thursday, January 03, 2002 9:05 AM
Subject: Fw:

>
> ----- Original Message -----
> From: <oetech@fccsun34w.fcc.gov>
> To: <jack@trclab.com.tw>
> Sent: Thursday, January 03, 2002 2:44 AM
>
>
> > To: JACK TSAI, TRAINING RESEARCH CO., LTD.
> > From: Joe Dichoso
> > jdichoso@fcc.gov
> > FCC Application Processing Branch
> >
> > Re: FCC ID O2BSDC6211
> > Applicant: Solomon Wireless Tech. Corp.
> > Correspondence Reference Number: 21611
> > 731 Confirmation Number: EA101948
> >
> >
> > Originally requested on 11/20/01. No extensions will be afforded.
> >
> > 1)) The New Body worn SAR data shows that the EUT position was not
> > performed at the proper distance using the accessory. The test should be
> > performed with the supplied belt clip and the belt clip against the flat
> > phantom. The new SAR data indicates 2 cm distance.
> > Please correct. Provide a photo of the Body worn test setup.
> > Please see the attached files.
> >
> > 2) The RF safety statement in the user manual must agree with the SAR
> > testing.
> > The last RF statement indicated 20 cm distances and 0.8 cm. Please
> > correct in accordance with the SAR test in item 1, above.

The statement in page 7 of user manual is corrected as follow :

CAUTION: To maintain compliance with the FCC's RF exposure guidelines, this equipment should be installed and operated with minimum distance 20cm between base unit's antenna and your body. And if worn on belt clip, use only the provided belt clip to maintain minimum distance of 1cm. Use only the supplied antenna. Unauthorized antenna, modification, or attachments could damage the transmitter and may violate FCC regulations.

> >

- > >
- > >
- > > The items indicated above must be submitted before processing can continue
- > on the above referenced application. Failure to provide the requested
- > information within 60 days of the original e-mail date may result in
- > application dismissal pursuant to Section 2.917 (c) and forfeiture of the
- > filing fee pursuant to section 1.1108.
- > >
- > > DO NOT reply to this e-mail by using the Reply button. In order for your
- > response to be processed expeditiously, you must upload your response via
- > the Internet at www.fcc.gov, Electronic Filing, OET Equipment Authorization
- > Electronic Filing. If the response is submitted through Add Attachments, in
- > order to expedite processing, a message which informs the processing staff
- > that a new exhibit has been submitted must also be submitted via Submit
- > Correspondence. Also, please note that partial responses increase
- > processing time and should not be submitted.
- > >
- > > Any questions about the content of this correspondence should be directed
- > to the e-mail address listed below the name of the sender.
- >