



Intertek Testing Services

ETL SEMKO

Report No.: 0308217

Tested By: Hong, Report No.: 0308217

Scan Settings (1 Range)

|----- Frequencies -----|----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB


Final Measurement: x QP / + AV

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.:



Intertek Testing Services

ETL SEMKO

Report No.: 0308217

Tested By: Hong, Report No.: 0308217

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement

Frequency	QP Level	QP Limit
-----------	----------	----------

MHz	dBuV	dBuV
-----	------	------

0.15000	53.9	66.0
---------	------	------

0.21000	48.6	63.2
---------	------	------

0.34500	35.1	59.1
---------	------	------

0.41500	29.7	57.6
---------	------	------

Frequency	AV Level	AV Limit
-----------	----------	----------

MHz	dBuV	dBuV
-----	------	------

no Results

* limit

Ctrl No.: