


Registration number: W6M22305-22655-C-1

FCC ID: O3I-A56WG040Z5

IC: 10365A-A56WG040Z5


Internal Photos



Registration number: W6M22305-22655-C-1

FCC ID: O3I-A56WG040Z5


IC: 10365A-A56WG040Z5



Registration number: W6M22305-22655-C-1

FCC ID: O3I-A56WG040Z5

IC: 10365A-A56WG040Z5






Registration number: W6M22305-22655-C-1

FCC ID: O3I-A56WG040Z5

IC: 10365A-A56WG040Z5






Registration number: W6M22305-22655-C-1

FCC ID: O3I-A56WG040Z5


IC: 10365A-A56WG040Z5



Registration number: W6M22305-22655-C-1

FCC ID: O3I-A56WG040Z5


IC: 10365A-A56WG040Z5



Registration number: W6M22305-22655-C-1

FCC ID: O3I-A56WG040Z5


IC: 10365A-A56WG040Z5



Registration number: W6M22305-22655-C-1

FCC ID: O3I-A56WG040Z5


IC: 10365A-A56WG040Z5



Registration number: W6M22305-22655-C-1

FCC ID: O3I-A56WG040Z5

IC: 10365A-A56WG040Z5





Worldwide Testing Services(Taiwan) Co., Ltd.

Registration number: W6M22305-22655-C-1

FCC ID: O3I-A56WG040Z5

IC: 10365A-A56WG040Z5

