











11AX20MIMO_Ant4a_7095




11AX20MIMO_Ant5a_7095






11AX40MIMO_Ant4a_5965




11AX40MIMO_Ant5a_5965






11AX40MIMO_Ant4a_6165




11AX40MIMO_Ant5a_6165






11AX40MIMO_Ant4a_6405




11AX40MIMO_Ant5a_6405






11AX40MIMO_Ant4a_6445




11AX40MIMO_Ant5a_6445






11AX40MIMO_Ant4a_6485




11AX40MIMO_Ant5a_6485






11AX40MIMO_Ant4a_6525




11AX40MIMO_Ant5a_6525






11AX40MIMO_Ant4a_6565




11AX40MIMO_Ant5a_6565






11AX40MIMO_Ant4a_6685




11AX40MIMO_Ant5a_6685






11AX40MIMO_Ant4a_6845




11AX40MIMO_Ant5a_6845







11AX40MIMO_Ant4a_6885




11AX40MIMO_Ant5a_6885








11AX40MIMO_Ant4a_6965




11AX40MIMO_Ant5a_6965






11AX40MIMO_Ant4a_7085




11AX40MIMO_Ant5a_7085








11AX80MIMO_Ant4a_5985





11AX80MIMO_Ant5a_5985















11AX80MIMO_Ant4a_6625




11AX80MIMO_Ant5a_6625






11AX80MIMO_Ant4a_6705




11AX80MIMO_Ant5a_6705






11AX80MIMO_Ant4a_6785




11AX80MIMO_Ant5a_6785






11AX80MIMO_Ant4a_6865



Date: 7.NOV.2022 23:22:48


11AX80MIMO_Ant5a_6865




Date: 7.NOV.2022 23:23:53



11AX80MIMO_Ant4a_6945




11AX80MIMO_Ant5a_6945






11AX80MIMO_Ant4a_7025



Date: 7.NOV.2022 23:42:32

11AX80MIMO_Ant5a_7025



Date: 7.NOV.2022 23:43:35

