



# Intertek Testing Services

## ETL SEMKO


0014084  
Report No.: TALK  
MODE Markbri

Tested By: Hong, Report No.: 0014084 Markbri  
Scan Settings (1 Range)

| Frequencies |      |      | Receiver Settings |          |        |       |        |          |
|-------------|------|------|-------------------|----------|--------|-------|--------|----------|
| Start       | Stop | Step | IF BW             | Detector | M-Time | Atten | Preamp | OpRge    |
| 450k        | 30M  | 5k   | 10k               | PK       | 20ms   | AUTO  | LN     | OFF 60dB |

Final Measurement: x QP  
Meas Time: 1 s  
Subranges: 16  
Acc Margin: 20dB

| Transducer No. | Start | Stop | Name   |
|----------------|-------|------|--------|
| 21             | 9k    | 30M  | EW0698 |





# Intertek Testing Services

## ETL SEMKO

Report No.: *0014084*  
TALK  
MODE *Markham*

Tested By: Hong, Report No.: *0014084 Markham*  
Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|  
Start Stop Step IF BW Detector M-Time Atten Preamp OpRge  
450k 30M 5k 10k PK 20ms AUTO LN OFF 60dB  
Final Measurement

no Results