



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

APPENDIX H: INTERNAL PHOTOGRAPHS



PHOTOGRAPH 10: INSIDE FRONT COVER WITH KEYPAD



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 11: FRONT OF KEYPAD



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 12: BACK OF KEYPAD




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 13: BACK OF FRONT COVER WITH KEYPAD REMOVED




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 14: INSIDE REAR COVER WITH ANTENNA REMOVED



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 15: INSIDE BACK COVER WITH ANTENNA




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 16: FRONT COVER REMOVED




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 17: BACK OF PLASTIC HOLDDOWN



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 18: FRONT OF PLASTIC HOLDDOWN




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 19: FRONT OF PCB WITH PLASTIC HOLDDOWN




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 20: FRONT OF PCB




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 21: UNDER LCD/SPEAKER ASSEMBLY (UPPER FRONT PCB)




360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 22: BACK OF PCB WITH SHIELDS



360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>



PHOTOGRAPH 23: BACK OF PCB WITH SHIELDS REMOVED