


TITLE: PLI Evaluation Report (RFI) **FCC ID: 0725346T (Pending)**
DRAWING: Q534615W.DWG
BY: Laura Bramschreiber and Phuong Nguyen

Page 25 of 41
Issued: 20 Feb 2005
Approved: Lee Pulver


FIGURE 7: PLI Photograph Number 5346C2934SJ-05 illustrates the bottom chassis removed showing components inside and the cabling.



TITLE: PLI Evaluation Report (RFI) **FCC ID: 0725346T (Pending)**
DRAWING: Q534615W.DWG
BY: Laura Bramschreiber and Phuong Nguyen

Page 26 of 41
Issued: 20 Feb 2005
Approved: Lee Pulver

FIGURE 8: PLI Photograph Number 5346C2934SJ-03 illustrates the component side of the Sensor board, TCS1CD.



TITLE: PLI Evaluation Report (RFI) **FCC ID: 0725346T (Pending)**
DRAWING: Q534615W.DWG
BY: Laura Bramschreiber and Phuong Nguyen

Page 27 of 41
Issued: 20 Feb 2005
Approved: Lee Pulver

FIGURE 9: PLI Photograph Number 5346C2934SJ-04 illustrates the component side of the Input/Output board, TCRP v1.0.

