



In the event that there is a driver conflict during installation, it is recommended that you keep the files.

Click **'Yes'** to continue.




Fig 8-4



Certain computers may require additional Windows ME installation files. Whenever this prompt appears, insert the WINDOWS ME CD-ROM into your CD-ROM drive and specify the location as:

d:\win9x

(d:\ is the drive designated to your CD-ROM drive.)

Click **'OK'** to continue.



Fig 8-5

- 4) Windows has finished installing the drivers for *AlphaCam Plus*.

Click **'Finish'** to continue.



Fig 8-6

- 5) Please restart the computer in order to load the new drivers.

Click **'Yes'** to continue.



Fig 8-7

9. Camera Installation(Windows 2000)

AlphaCam plus

- 1) Plugging in the camera will prompt a 'New Hardware Wizard'to appear.

Click '**Next**' to continue.



Fig 9-1

- 2) Windows will now search on the hard drive for the best drivers. Please select 'Search for the best driver for your device (Recommended)'.

Click '**Next**' to continue.




Fig 9-2

- 3) Windows will search a location for the device driver. Make sure the only box with a check is 'Specify a location'.

Click '**Next**' to continue.




Fig 9-3

- 4) Make sure to 'Copy Manufacturer's File From':

`c:\winnt\temp\usbdrivers\`

Click '**OK**' to continue.




Fig 9-4