



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

May 6, 2004

RE: Global Sun Technology Inc.

FCC ID: O7J-WL012454-NM

After a review of the submitted information, I have a few comments on the above referenced Application.

Administrative/General:

- 1) Please provide a cover letter describing and detailing the changes of this unit compared to the unit originally approved as soon as possible.
- 2) The test report suggests that the change in the device is the antenna gain. However, the report documents 0 dBi, which is identical to the original gain as well. Please explain.
- 3) There appears to be a large unexpected change to the SAR value. Please provide an explanation for this unexpected change. If applicable, please provide internal photographs showing the difference of the EUT's, especially in the area around the antennas.
- 4) The SAR Report appears incomplete. All information typically provided in the appendixes (i.e. SAR Plots, System calibration certificates, photo of test configurations, etc.) appear to be missing.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.