



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 20, 2003

RE: Handspring Inc.

FCC ID: O8FBW

After a review of the submitted information, I have a few comments on the above referenced Application.

Part 15 Class B review

- 1) The cover page and explanation of limits in the front of the report all show FCC Class B. However, all limits and test distances applied are per the EN55022 Class standard without any explanation. Please explain.
- 2) Please provide the test photographs as part of a separate exhibit.
- 3) From looking at the operational description, it appears that this device (not including the transceivers) has a 144 MHz clock. According to 15.33(b)(1), this requires digital device emissions testing to be performed up to 2 GHz. It does not appear that this testing was performed. Note that EN55022 does not have this requirement.
- 4) Please provide the RBW and VBW settings used for the following:
 - a) 30 - 1000 MHz Radiated
 - b) > 1000 MHz Radiated
 - c) 0.15 - 30 MHz Conducted

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.