

FCC REQUIREMENTS

EQUIPMENT NOTES

This equipment is registered with the Federal Communications Commission and is in compliance with Part 68 of the FCC Rules and Regulations. On the bottom of this equipment is a label indicating among other information, the FCC Registration Number and Ringer Equivalence Number (REN) for this equipment. Upon request, you must provide this information to your telephone company. The REN is useful to determine the quantity of devices you may connect to your telephone line and still have all of those devices ring when your telephone number is called. In most, but not all areas, the sum of the REN'S of all devices connected to one line should not exceed five(5).

- The IBM-3330 telephone cannot be used on coin service pay telephones.
- The IBM-3330 telephone cannot be connected to party lines.
- The IBM-3330 telephone is Hearing Aid Compatible.

If you experience trouble with this telephone equipment, disconnect it from the telephone network until the problem has been corrected. The telephone company may discontinue service if your telephone equipment causes harm to the telephone network. In this case, the telephone company will:

- Notify the customer that service is being discontinued.
- Provide the customer with the opportunity to correct the situation.
- Inform the customer of their right to file a complaint with the FCC.

Warning: Changes or modifications not expressly approved by the party responsible for its compliance could void the user's authority to operate the equipment.

Some cordless telephones operate at frequencies that may cause interference to nearby TV's and VCR's. To minimize or prevent such interference, the base of the cordless telephone should not be placed on or near a TV or VCR. If interference is experienced, moving the cordless telephone farther away from the TV or VCR will often reduce or eliminate the interference.

INTERFERENCE INFORMATION

This equipment generates and uses and can radiate low level radio frequency energy. It has been tested and found to comply with the limits for a Class B digital device in accordance with the specifications in Part 15 of the FCC Rules, which are designed to provide reasonable protection against such interference in a residential installation. If this equipment does cause interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient the radio or TV receiving antenna.
- Relocate this device with respect to the receiver.
- Move this device away from the receiver.

If necessary, the user should consult the dealer or an experienced radio/television technician for additional suggestions. The user may find the following booklet, prepared by the Federal Communications Commission, helpful. This booklet is available from the U.S. Government Printing Office. There may be a charge for this booklet.

"How to Identify and Resolve Radio-TV Interference Problems"

U.S. Government Printing Office
Washington, D.C. 20402
Stock Number, 004-000-00345-4