

Scott McCutchan

From: Scott McCutchan [scott@celectronics.com]
Sent: Tuesday, December 11, 2001 6:06 PM
To: agoura@celectronics.com
Cc: Ruby Hall
Subject: FCC ID: OARTXAM01

Mr. Madlangbayan,

In order for processing of this application (FCC ID: OARTXAM01) to continue, the following issue(s) will have to be addressed:

- 1) The sample FCC label shows that the FCC Identifier is used improperly. Pursuant to section 2.925(a)(1) of the rules, the term "FCC ID:" must be followed by the actual FCC ID on the same line (Example: FCC ID: XXX-XXX). On the sample label, "FCC ID:" is shown above the actual identifier. A new sample diagram in the correct format must be submitted.
- 2) The block diagram should show the frequency of all oscillators used in the device at each block as per 2.1033(b)(5). Please submit a new block diagram which meets all the requirements of this section.
- 3) The operating frequency listed on the application form and in the test report indicates that the device operates on only one channel, but the user's manual indicates that the device operates on three channels. Please clarify.
- 4) Please submit duty cycle plot(s) showing the claimed 32% duty cycle.
- 5) Please indicate whether the device complies with all of the operational limitations contained in 15.231(a).

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to scott@celectronics.com.

If you have any questions, feel free to contact me.

Best regards,

Scott McCutchan
Lab Manager
Compatible Electronics, Brea Division
(714) 579-1489
fax (714) 579-1850
<http://www.celectronics.com>