

Tune Up Procedure

1. OBAPA1011

- AFTER PRESSING THE PTT AND CHECK THE TX POWER AT THE CH. 1,
ADJUST R505 OR C501 TO MEET 0.5W