

Tune Up Procedure

1. OBAPH1007

- AFTER PRESSING THE PTT AND CHECK THE TX POWER AT THE CH. 1,
ADJUST R505 OR C501 TO MEET 0.45W