

Report No.: 9810658

Tested By: Hong, Report No.: 9810658

Scan Settings (1 Range)


Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

dBuV $\diamond$ Mkr : 460.00 kHz 44.1 dBuV



Ctrl. No.: N/A

Report No.: 9810658

Tested By: Hong, Report No.: 9810658

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
0.45000	37.5	48.0
0.59000	32.2	48.0
0.79000	28.8	48.0
0.99000	25.9	48.0

* limit exceeded

Ctrl. No.: N/A